Verbindungstechnik

Scl	heiben ohne Fase (A	usführung mittel)		DIN 1	25 A / ISO 7089	
	Optional: Edelstahl A4 -ES					
/					f.·.	
S lyp S	Stahl Typ Edelstah inkt A2	d1	d2		für Schrauben	
7 werz		3,2	d2 7	0,5	M 3	
125/		4,3	9	0,8	M 3	
1 1		5,3	10	1,0	M 5	
s 125/		6,4	12	1,6	M 6	
125/		8,4	16	1,6	M 8	
Rost 10 125/		10,5	20	2,0	M 10	
		13,0	24	2,5	M 12	
125/		15,0	28	2,5	M 14	
125/		17,0	30	3,0	M 16	
125/		19,0	34	3,0	M 18	
The state of the s	A-20 125A-20 ES	21,0	37	3,0	M 20	
125/		23,0	39	3,0	M 22	
11111111	A-24 125A-24 ES	25,0	44	4,0	M 24	
125/		28,0	50	4,0	M 27	
	A-30 125A-30 ES	31,0	56	4,0	M 30	
	A-33 125A-33 ES	34,0	60	5,0	M 33	
	A-36 125A-36 ES	37,0	66	5,0	M 36	
125/		40,0	72	6,0	M 39	
125/	A-42 125A-42 ES	43,0	78	7,0	M 42	
₽ E	Bestellbeispiel andere Ge		Kennzeichen der Opt	ionen:		
	Stando	ardtyp	Edelstahl A4	ES4A		
Scl	Scheiben mit Fase (Ausführung mittel)			DIN 125 B / ISO 7090		
Typ S	Stahl	für	Typ Stahl		für	
/ verz	inkt d1 d2	s Schrauk	oen verzinkt	d1 d2	s Schraub	
125	B-5 5,3 10	1,0 M 5	125B-18	19,0 34	3,0 M 18	
<u>s</u> 125	B-6 6,4 12	1,6 M 6	125B-20	21,0 37	3,0 M 20	
125	B-8 8,4 16	1,6 M 8	125B-22	23,0 39	3,0 M 22	
1258	B-10 10,5 20	2,0 M 10	125B-24	25,0 44	4,0 M 24	
1258	B-12 13,0 24	2,5 M 12	125B-27	28,0 50	4,0 M 27	
1258	B-14 15,0 28		125B-30	31,0 56	4,0 M 30	
125	B-16 17,0 30	3,0 M 16				
Scl	Scheiben für Zylinderschrauben			DIN 433 / ISO 7092		
Тур \$	Stahl Typ Edelstah	1 Cross			für	
verz	inkt A2	d1	d2	S	Schrauben	
433-		3,2	6	0,5	M 3	
433-	-4 433-4 ES	4,3	8	0,5	M 4	
433-	-5 433-5 ES	5,3	9	1,0	M 5	
433-		6,4	11	1,6	M 6	
433-		8,4	15	1,6	M 8	
122		10,5	18	1,6	M 10	
rost/° 433-		13,0	20	2,0	M 12	
433-		15,0	24	2,5	M 14	
433-		17,0	28	2,5	M 16	
433-		19,0	30	2,5	M 18	
433-		21,0	34	3,0	M 20	
, Sch	heiben, groß			DIN 9021-10	OHV / ISO 7093	
Тур \$	Stahl Typ Edelstah				für	
Typ \$ verz	Stahl Typ Edelstah inkt A2	d1	d2	s	für Schrauben	
Typ \$ verz 902	Stahl Typ Edelstah inkt A2 1-3 9021-3 ES	d1 3,2	9	s 0,8	für Schrauben M 3	
Typ \$ verz 902 902	Stahl inkt Typ Edelstah A2 1-3 9021-3 ES 1-4 9021-4 ES	d1 3,2 4,3	9 12	s 0,8 1,0	für Schrauben M 3 M 4	
Typ \$ verz 902 902 902	Stahl inkt Typ Edelstah A2 1-3 9021-3 ES 1-4 9021-4 ES 1-5 9021-5 ES	d1 3,2 4,3 5,3	9 12 15	s 0,8 1,0	für Schrauben M 3 M 4 M 5	
Typ \$ verz 902 902 902 902 902 902	Stahl Typ Edelstah inkt A2 1-3 9021-3 ES 1-4 9021-4 ES 1-5 9021-5 ES 1-6 9021-6 ES	d1 3,2 4,3 5,3 6,4	9 12 15	s 0,8 1,0 1,2 1,6	für Schrauben M 3 M 4 M 5 M 6	
Typ \$ verz yez yez yez yez yez yez yez yez yez ye	Stahl Typ Edelstah inkt A2 1-3 9021-3 ES 1-4 9021-4 ES 1-5 9021-5 ES 1-6 9021-6 ES 1-8 9021-8 ES	d1 3,2 4,3 5,3	9 12	\$ 0,8 1,0 1,2 1,6 2,0	für Schrauben M 3 M 4 M 5	
Typ \$ verz 902 902 902 902 902 902 902	Stahl Typ Edelstah inkt A2 1-3 9021-3 ES 1-4 9021-4 ES 1-5 9021-5 ES 1-6 9021-6 ES 1-8 9021-8 ES	d1 3,2 4,3 5,3 6,4	9 12 15	s 0,8 1,0 1,2 1,6	für Schrauben M 3 M 4 M 5 M 6	
Typ \$ verry 902 902 902 902 902 902 902 902	Stahl Typ Edelstah inkt A2 1-3 9021-3 ES 1-4 9021-4 ES 1-5 9021-5 ES 1-6 9021-6 ES 1-8 9021-8 ES 1-10 9021-10 ES	d1 3,2 4,3 5,3 6,4 8,4	9 12 15 18 24	\$ 0,8 1,0 1,2 1,6 2,0	für Schrauben M 3 M 4 M 5 M 6 M 8	
Typ \$ verz 902 902 902 902 902 902 902 902 902	Stahl Typ Edelstah inkt A2 1-3 9021-3 ES 1-4 9021-4 ES 1-5 9021-5 ES 1-6 9021-6 ES 1-8 9021-8 ES 1-10 9021-10 ES 1-12 9021-12 ES	d1 3,2 4,3 5,3 6,4 8,4 10,5	9 12 15 18 24 30 37	\$ 0,8 1,0 1,2 1,6 2,0 2,5 3,0	für Schrauben M 3 M 4 M 5 M 6 M 8 M 10 M 12	
Typ \$ verz 902 902 902 902 902 902 902 902 902 902	Stahl Typ Edelstah inkt A2 1-3 9021-3 ES 1-4 9021-4 ES 1-5 9021-5 ES 1-6 9021-6 ES 1-8 9021-8 ES 1-10 9021-10 ES 1-12 9021-12 ES 1-14 9021-14 ES	d1 3,2 4,3 5,3 6,4 8,4 10,5	9 12 15 18 24 30	\$ 0,8 1,0 1,2 1,6 2,0 2,5	für Schrauben M 3 M 4 M 5 M 6 M 8	
Typ \$ verz 902 902 902 902 902 902 902 902 902 902	Stahl Typ Edelstah inkt A2 1-3 9021-3 ES 1-4 9021-4 ES 1-5 9021-5 ES 1-6 9021-6 ES 1-18 9021-8 ES 1-10 9021-10 ES 1-12 9021-12 ES 1-14 9021-14 ES 1-16 9021-16 ES	d1 3,2 4,3 5,3 6,4 8,4 10,5 13,0 15,0	9 12 15 18 24 30 37 44	\$ 0,8 1,0 1,2 1,6 2,0 2,5 3,0 3,0 3,0	für Schrauben M 3 M 4 M 5 M 6 M 8 M 10 M 12 M 14 M 16	
Typ \$ verz 902 902 902 902 902 902 902 902 902 902	Stahl Typ Edelstah inkt A2 1-3 9021-3 ES 1-4 9021-4 ES 1-5 9021-5 ES 1-6 9021-6 ES 1-8 9021-8 ES 1-10 9021-10 ES 1-12 9021-12 ES 1-14 9021-14 ES 1-16 9021-16 ES 1-18 9021-18 ES	d1 3,2 4,3 5,3 6,4 8,4 10,5 13,0	9 12 15 18 24 30 37 44 50	\$ 0,8 1,0 1,2 1,6 2,0 2,5 3,0 3,0	für Schrauben M 3 M 4 M 5 M 6 M 8 M 10 M 12 M 14	

10